

MCI Coach Emergency Exit Decals

INFORMATION SHEET

nfi.parts



Don't let a coach go out of service due to a missing decal.

All emergency exits must be clearly identified.
Replace worn/missing emergency exit markings for D.O.T. compliance.



NFI Part No.	Description
03-15-1427	DECAL-PASS WINDOW RELEASE
03-15-1428	DECAL-EMERG.EXIT,RH
03-15-1429	DECAL-EMERG.EXIT,LH
03-15-1431	DECAL-EMERG.EXIT,FRENCH
03-15-1432	DECAL-EMERG.EXIT,SPANISH

Other decals and placards available:

NFI Part No.	Description
03-15-2018	DECAL-COURTESY SEATING
03-15-5363	DECAL-ROOF HATCH,INSTRUCTIONS, SP
03-15-5368	DECAL-ROOF HATCH,INSTRUCTIONS, SP
03-15-5640	DECAL-EMERG.EXIT,HATCH,ENGLISH/ SPANISH
03-15-7257	NAMEPLATE-EMERG.EXIT,ENGLISH,LH
03-15-7258	NAMEPLATE-EMERG.EXIT,ENGLISH,RH
03-15-7261	NAMEPLATE-SPANISH,LH,E/J COACH
03-15-7262	NAMEPLATE-SPANISH,RH,E/J COACH
03-15-7274	NAMEPLATE-EMERG.EXIT,ENGLISH
03-15-7276	NAMEPLATE-EMERG EXIT,SPANISH
03-15-7278	NAMEPLATE-COURTESY SEATING
19-13-24PK	RIVET-DOMED,BRK MAN PK=100 PCS.

Information on this sheet is subject to change at the discretion of NFI Parts and/or its affiliates. Contact your NFI Parts solutions manager or customer service representative for further details.

nfi.parts
www.nfi.parts



U.S. & Canada
800.665.2637



U.S. 800.323.1290
Canada 800.665.0155
partsstore.mcicoach.com